## **VME BPM**

	2020-10					2020-11					2020-12				2021-1					2021-2				2021-3			
		41 4	2 4	43	44 4	15	46	47	48	49	50	51	52	53	1	2	3	4	5		6	7	8	9	10	11	12
AD Instrumentation		AD Ir	stru	mer	ntation	1							•														
VME BPM																											
Add nodes to save list		New																									
Move scaling into the frontend	New																										
VP94 and HP103 show identical data when ()	New																										
Release 201603A		New																									
Upgrade ClassACNet/Mooc		Assiç	jned																								
SY BPMs won't boot		Reso	lved																								
F4 node won't boot		New																									
Replace SBC at F4		Reso	lved																								
BBM Interface		Assiç	jned																								
Attenuation tables won't initialize ()		Reso	lved																								
Improvements for auto-tune operation		New																									
Flat positions being reported intermittently		New																									
Put together a test stand		New																									
Establish alarms for SBPMxx nodes		New																									
ACNET support for beam threshold		New																									
Error state during spill		New																									
Investigate reading back attenuator ()		New																									
Improve error handling of CAN bus ()		New																									

10/19/2020 1/1